


YUASA FS-C Packing List Mechanical Endurance Testing System

v4

Packing List for YUASA Jig FS-C

1. 1 x First Step Guide DLDMLH-FS
2. 1 x DMX-FS-C Jig with Cartridge installed
3. 1 x Safety Cover
6. 1 x Floating Joint [ET136A001-004] 
5. 1 x Safety Interlock Cable 
4. Joint Bracket
7. 2 x Washer Assembled Cap Screws M4x10, (3 mm Allen Wrench), (the screws should be on the Jig in the mounting holes that connect the Jig to the Motor Unit Joint Bracket). 

The Jig should be fully assembled in the shipping box. The Cartridge should be attached to the Jig held with the four thumbscrews. The Tilt Controllers and the Clamping Plates should be attached to the Jig. The Washer Assembled Cap Screws should be attached to the Jig. If you are shipping the Jig, these items may have been removed during use and they must be put back in place before shipping. This drawing shows each of the pieces that are part of the Jig.



No	NAME	TYPE	MANUFACTURE (MATERIAL)	NOTE
1	Basic unit, tension-free folding	ET254A002-010	YUASA SYSTEM	
2	Cartridge	ET254A007-001	YUASA SYSTEM	
3	Handling Plate	ET200P214-005	YUASA SYSTEM	
4	Knurled thumb screw	RNCB4-5-10	MISUMI	
5	Tilt controller	ET200P165-006	YUASA SYSTEM	
6	Support, tilt controller	ET200P170-002+P170-006	YUASA SYSTEM	
7	Extra low head cap screw	CBSM5-12	MISUMI	
8	Clamping plate	ET200P005-045+P006-006	YUASA SYSTEM	
9	Safety Cover	ET500A003-025	YUASA SYSTEM	For Test Jig